



## INDUSTRIAL SKILLS TEST 1, 2 & 3

- Inspect and set-up CLEMCO Abrasive Blasting Pot, deadman controls and respiratory equipment. Perform all necessary safety checks and pre-operational procedures, including checking blast nozzle for wear.
- Check and record air temperature, humidity, dew point and surface temperature of the ASTM 4228 mock-up
- Blast **both sides** and all angles of the ASTM mock-up to a “SP-10” standard  
**(stop at the bottom of the steel panel, it is not necessary to blast or coat the feet of the mock-up)**
- “Blow-down” to remove surface dust from mock-up
- Check surface profile and record
- Using a forklift, move mock-up panel to the spray booth for the spray painting portion of the test
- **Operator is required to use all personal protective equipment necessary to complete the tasks safely.**