



SKILLS TEST 6 & 7

- Using SSPC VIS-3, verify pre-condition of steel on the small industrial mock-up and record
- Using the powered hand tools, (needle gun & grinder) prepare at least 2 square feet of steel surface for each tool to a SSPC SP-11 standard
- Verify the specifications have been achieved by using the VIS-3 visual comparator and record
- Check and record air temperature, humidity, dew point & surface temperature of the mock-up
- Remove dust and debris from mock-up
- **Operator is required to use all personal protective equipment necessary to complete the tasks safely.**